

① 4 missing people

② MAPS ARE NOT UP TO DATE

③ There is a split shaft
in #2 entry 2XC in by
Fresh Air Base A EXHAUSTED
FAN ON RETURN shaft
OFF

4 FRESH AIR MUST REMAIN ACROSS
the Fresh Air Base to vent the mine

1 Locate All missing Miner.

2 Bring SURVIVORS to FAB

3 Make the mine entirely

4 The RETURN FAN at shaft
can be turned on/off Not Reversed





